CabMaster Premium Library Build 30 Autoupdater Details

New Features

CMPREM30-I134	Shadow Rails: Option to show L-Shaped return
CMPREM30-I123	Labour Tables: Default values for labour lookups
CMPREM30-I101	Benchtop Extras Cabinet: Add hardware fields
CMPREM30-I71	Floor Division: Add oversize options for fixing rail notches in divisions for shadow
CMPREM30-I70	Tall Wall oven: Adjust upper and lower handles independently
CMPREM30-I69	Corner Benchtop: Option for substrate below benchtop
CMPREM30-I62	Vanity cabinets: Option to select door materials for vanity panels
CMPREM30-I57	Drawer Standard: Ability to "Extend Ends Backwards"
CMPREM30-I56	Polyshape: Add benchtop as a material choice
CMPREM30-I55	Defined Cutouts: Add checkbox for 'stretch to fill'
CMPREM30-I54	PipeChase: Ability to place Adjustable Shelf holes in the pipe chase front
CMPREM30-I47	All Cabinets: Material Tags
CMPREM30-I115	Floor Corner: Allow greater internal angle than 180deg
CMPREM30-I30	Door and Drawer handles: Ability to turn on or off Handles for doors and drawers independently
CMPREM30-I13	Wall Standard: Remove extra holes from back when using pipe chase
CMPREM30-I12	Vanity cabinets: Add splashback controls

Bug Fixes

CMPREM30-I131	Universal Shelves: Top and Bottom Error
CMPREM30-I130	All Parts: Every part being treated as a "Shape" for Manufacture
CMPREM30-I127	Job Defaults Page: Recursive formula
CMPREM30-I126	Door Profiles: 3d machining view sticks off part
CMPREM30-I108	Various Floor and Vanity Cabinets: Rail still showing in MachViewList when removed
CMPREM30-I100	Universal1: Can't view sloped top in machine view
CMPREM30-I98	Floor Return Right: Shelf - Corner format doing unwanted drilling on left end
CMPREM30-I97	Wall Universal: Machviewlist errors fixed
CMPREM30-I95	Profile doors: Veins close to edge not showing in 3d view / clearance moving veins too far
CMPREM30-I94	Door Profiles: Veins full depth in 3d textured view

CMPREM30-I42	Wall Oven Drawer: Drawer front drilling missing on Drawers beyond drawer 1
CMPREM30-I129	All Cabinets: Plan view showing through depth penetration
CMPREM30-I128	Tall Wall Ovens: Oven Frame Stiles Error
CMPREM30-I125	Vanity Drawer and Vanity Sink Drawer: Labour & Construction Page Error
CMPREM30-I124	Donated machining: Holes not donating
CMPREM30-I122	Parts Library Shelf: Front left chamfer/radius with T&G Construction
CMPREM30-I121	Blank Drawers: Unable to view machining of drawer front
CMPREM30-I120	Drawing Properties: Legs page missing
CMPREM30-I119	Tall Split Returns: Unnecessary floating shadow rail notch out in upper ends
CMPREM30-I118	Shelf Corner: Oversizes not working correctly
CMPREM30-I116	Machine View Lists: Various parts still showing when removed from cabinet
CMPREM30-I114	Floor Corner cabinets: shelves/bottoms explode on 181+ degrees
CMPREM30-I113	Splay R Cabinets: Top Construction Holes Not Lining Up
CMPREM30-I112	Universal Cabinets: Lip holes applying to non-lipped shelves / only applied when 'All As #1' selected
CMPREM30-I110	Floor Standard: holes for top of sink mullion incorrectly positioned
CMPREM30-I107	Errors:"PdrwPriceArr" Erroring on all drawings
CMPREM30-I106	Floor Drawer and Vanity Cabinets: Local carcass cutlist fails when top is removed
CMPREM30-I105	Tall Blind Return: Continuous shelf holes too far forward in End Left
CMPREM30-I104	Tall Blind Return: No hinge holes on Lower Door
CMPREM30-I102	Tall Angled: Front legs incorrectly positioned
CMPREM30-I99	Universal1: Setting top width to 0mm removes sloped top / re-enabling adds extra top piece
CMPREM30-I96	Tall Standard: Bifold doors - Hinge plate holes still present after hinge holes turned off
CMPREM30-I93	DoorMaster-LT: Vein Doors with Quantity specified not correct in 3D
CMPREM30-I92	Tall Corner: Missing Fixed Shelf Holes if Gap From Sides greater than zero
CMPREM30-I91	Tall Corner: Adjustable shelves made into fixed shelves are too large
CMPREM30-I90	Tall Broom: Putting construction holes on front of base when lower shelves are on left
CMPREM30-I89	Tall Split Broom: Door gaps misalignment on friendly page when not using lower doors
CMPREM30-I88	Tall Split Broom: 'Remove Top Carcass' causes incorrect carcass sizes
CMPREM30-I86	Tall Split Drawer: Shaker Door settings button missing
CMPREM30-I85	Universal Cabinets: Shadow Rails Not showing in 3d/plan/textured/elevation
CMPREM30-I84	Shadow Rails: Pressouts not oversized by tool radius in universal cabinets
CMPREM30-I83	Tall Doors: Mid-rail listening to lower door height when using full doors
CMPREM30-I82	Back Rails: No construction holes from Back Rail into Back
CMPREM30-I81	Tall Angled Plus - Add Feet Controls at Cabinet Level

CMPREM30-I80	Tall Walk-in Pantries: Shaker Mid rail height
CMPREM30-I79	Tall Angled Walk-in Pantries: Kick Height added to bottom Shaker Rail Height in 3D view
CMPREM30-I78	Tall Cabinets: Extend to Ceiling Errors
CMPREM30-I77	Tall Drawer & Tall Split Drawer: Adjustable shelf gap applies to Fixed shelves when using Custom method
CMPREM30-I76	Wall Wine: Extend to Ceiling has shelves in wrong position and dividers too short
CMPREM30-I75	Kickboard Standard: Cam Holes erroring on ends
CMPREM30-I74	CM-Parts: Drawers - Edging error when Shadow Rails Added
CMPREM30-I73	Universal Cabinets: Kickboard Fascia not exporting
CMPREM30-I72	Pipe Chase: Edging Not correct when measuring to centre of chase from the right
CMPREM30-I68	3D View: Doors disappearing in 3D Wireframe and 3D Hidden view when using 'Make Glass Door'
CMPREM30-I67	Vanity Door Drawer: Vanity Panel and Shadow Rails, Division cutout is too large
CMPREM30-I66	Tall angled walk in pantry 2: When Skewing cabinet widths the door shows weird on the plan view
CMPREM30-I65	Wall Angled: Remove bottom not working
CMPREM30-I64	Wall Bulkhead: missing Labour Component
CMPREM30-I63	Template Visibilities: Fixing rails between drawers cannot be turned off in template visibilities
CMPREM30-I61	Tall Wall Ovens: Upper Doors overhanging bottom hinge always follows the door.
CMPREM30-I60	Drawing properties: display option for Filler colour not working correctly
CMPREM30-I59	Wardrobe Combo: Changing to 1 Door turns off top hinge plate
CMPREM30-I58	Standard Drawer Runners: TnG not compatible with Concealed runners
CMPREM30-I53	Metal and Premium Sink Drawers: Mid Back does not donate machining
CMPREM30-I52	Full Drawer Bank with Shadow Rails has panel holes too high
CMPREM30-I51	Splayed Standard Cabinets: Continuous shelf holes incorrect position
CMPREM30-I50	End Panels: text location
CMPREM30-I49	Tall Beverage & Tall Beverage Drawer: Errors when placing cabinet
CMPREM30-I48	Floor Corner Cabinets: Benchtop radius corner checkboxes not engaging radius
CMPREM30-I45	Floor 45Deg: Ends have no back
CMPREM30-I44	Floor Angled: Rail Front protrudes through End Left and isn't cut to required shape
CMPREM30-I43	Floor Angled Display: Changing to Fixed shelf still shows Adj shelf holes
CMPREM30-I41	Wall Fridge Cab: No construction drilling for Mullion

CMPREM30-I40	Floor Drawer: Error when "Add Doors" selected
CMPREM30-I39	Floor Drawer: Handle holes incorrect when adding doors
CMPREM30-I38	Benchtop and Benchtop Corner: Template not displaying colour
CMPREM30-I37	Tall Broom: Division protrudes through pipe chase area when present in Centre
CMPREM30-I36	Floor Division: 2 Door and 4 Door gaps left and right affect alignment to centre division
CMPREM30-I35	Floor Division: Division is cutting out for Shadow Rail and Rail at the back
CMPREM30-I34	Tall Broom: Continuous holes move forward on division when pipe chase present
CMPREM30-I33	Floor DrwDoor: Full Door For Drawer Fronts cutting wrong size of parts
CMPREM30-I32	All Cabinets: Leg hole pages are unable to control left and right legs independently
CMPREM30-I31	Tall Split Pantry: Hinge plate holes not moving with hinge holes
CMPREM30-I27	Universal Cabinets: Dowel Construction Not Using Correct Layer
CMPREM30-I26	Machine view part labels: line extends outwards when using units other than mm
CMPREM30-I25	Benchtop Corner: Substrate not displaying colour
CMPREM30-I23	Universal1: Special Cutouts require DvR choice
CMPREM30-I22	Tall drawers with shadow rails: Between gap label incorrect
CMPREM30-I21	CM-Robes Furn Floor Drawer Split: Shaker Profile not applying to all drawers
CMPREM30-I20	Universal Cabinets: Spacer rail construction holes machining at 0mm
CMPREM30-I19	Tall Drawer: Custom shelving recessed too far
CMPREM30-I18	Leg Data: Updated to handle Biesse Solid/Biesse Works Layers table requirements
CMPREM30-I17	Universals (and Robes): Shelf Lip section error
CMPREM30-I15	Universal1: Sloped Top is creating a second top
CMPREM30-I14	Wardrobe Shelf and Wardrobe Hanging: 3D Rails in wrong face
CMPREM30-I11	Wall Angled: Remove Bottom checkbox not functional
CMPREM30-I10	Tall Split Pantry: Cnt X & Y checkboxes not working for Lower Doors
CMPREM30-I9	Drawer Cabinets: Shadow rails inverting cutout when Appliance cutouts set to 'No' but ticked on
CMPREM30-I8	Janper Duraform Materials source: #ERR! evaluating #ERR!
CMPREM30-I7	Drawer Handles: Material listening to Drawer Bank at all times
CMPREM30-I6	Parts Library Door: Contains hardware "Brass wire"
CMPREM30-I5	Profile doors: Series 2 Style 3 - Spelling error
CMPREM30-I4	DoorMaster-LT: Vein Doors - Control of Veins in Upper pane of Pantry Doors
CMPREM30-I2	Bench Cabinets: Param2 has Formula in Name field (Except Appliance End Panel)